



RINA

TEST CERTIFICATE
CERTIFICATO DI COLLAUDO

N. 2013/RM/01/390-c1

RINA file No. 2013/RM/01/390
Pratica RINA N.

Manufacturer or Supplier: Cedrone Oleodinamica srl - San Giovanni Incarico (FR) - Italy
Fabbricante o Fornitore

Work order No.: =
Commessa N.

Purchaser: Cedrone Oleodinamica srl
Committente

Order No.: = Intended for: Stock
Ordine N. Destinazione

THIS IS TO CERTIFY that the items, particulars of which are given below, have been tested and found to be in compliance with the requirements of the RINA rules

SI CERTIFICA che gli oggetti / apparecchi, le cui caratteristiche sono di seguito indicate, sono stati sottoposti a collaudo e sono stati riscontrati conformi alle prescrizioni dei regolamenti del RINA .

The calibration status and adequacy of the test measurements devices used have been satisfactorily verified.

Lo stato di taratura e l'adeguatezza degli strumenti di misura utilizzati per il collaudo sono stati verificati con esito soddisfacente

Description of material and tests carried out:

Descrizione del materiale e prove eseguite:

N° 3 (three) hydraulic cylinders : one (code CLD1250901020MFX) dim 125x150 mm stroke 1020mm, two (code CLD1400800645OOX) dim 140x170mm and stroke 645mm.


Tests carried out with satisfactory results:

- Review of testing material certificates,
- Check of welding procedures approved by RINA and RINA Certificates' welders,
- visual and dimensional check in conformity of approved drawings n° : PPVT 16613, PPVT 16614 and PPVT 16612 dated 21.06.2013;
- witnessing to NDT tests – dye penetrant test;
- functional test on workshop bench;
- regulamentary hydrostatic test pressure: 27 Mpa
- markings.

Markings: <i>Marche apposte:</i>	 13 RM 390	Testing date: <i>Data collaudo:</i>	11/07/2013
-------------------------------------	---	--	------------

Enclosures: =
Allegati:

Issued at: Civitavecchia on: 11/07/2013
Rilasciato a: il:



RINA S.p.A.
S. MUCCI

RINA